




CERTIFICATE OF COMPLETION OF SUBSURFACE SEWAGE DISPOSAL SYSTEM

Issued to: Fowler Carey
Owner/Developer, Contractor, Installer, Etc.
 Location: Lot 5 Indian Sheldons
Delaware Pt.
II

Type of system
 1. Conventional
 2. Low Pressure Pipe
 3. Mound
 4. Lagoon
 5. Large Diameter Gravelless Pipe w/rock
(a) Sand backfill required Yes () No () Backfill
 6. Other _____
 (type) CRB (volume) 1000 Septic Tank
 Estimated Absorption Rate 75 (minutes per inch)
 New Installation Repair Other
 Installed by: Larry Luc

Fieldlines, tanks + tightline checked 6-3-03. Wiping permit obtained but no final yet. Total 370

2-20-03 Verified electrical inspection. System complete JMB



Construction Approved By: _____

[Signature]
 (Name and Title)

2-20-03
 (date)