

**May 15, 2018**

Thoroughbred Renovations & Transportation



1986 Somerset

1. Roof: integrity and condition are solid, gel coat on roof is in good condition, all rails and canopy supports are solid.
2. Bridge & lower helm: gauges are in good working order; all gauges are reading accurately.
3. Bridge & lower helm: shift and throttle controls are in good working order, good response.
4. Engines: Port & starboard engines are in good working order, start and respond well.
5. Generator: Generator is in good working order, all start and stop controls are working correctly.
6. Outer Cabin: All cabin walls are solid found no issues, all windows and cabin rail sealing is in good condition.
7. Outer hull: Hull is in good condition, no signs of any damage, integrity is good, engine compartment, cabin, and bow compartment show no signs of any leaks on any kind.
8. All front and rear deck support are solid.
9. All inlets: power, water is in good condition.
10. Navigation: All navigation lights are in working order.
11. Interior: Interior structure is solid, interior walls, paneling, cabinets are in good condition.
12. All electrical and plumbing are in good condition.
13. Interior cabin hull is dry, all wood structures and flooring are dry and clean.
14. Fresh water and holding tanks are in good condition.
15. All bilge pumps are in good working order.

Comments: This 86 Somerset overall is a good solid boat, it is in good condition and is drive ready.